US ERA ARCHIVE DOCUMENT

1. Incident Name		2. Date Prepared			. Time repared	UNIT LOG		
Kalamazoo River/Enbridge Spill		07/27/2012		17	700			ICS 214
4. <u>Unit Name/Designators</u>		5. Unit Leader			6. Operational Period :			
SOTF Team #7		Name:	Dan Capone & Joe Victory (START/US EPA)			From:	07/27/2012 0700 07/27/2012	
		Position: Operations Section Chief			To:	1600		
		7. Pe	rsonnel	Roste	er Assigned			
<u>Name</u>		ICS Position			DUTY CELL			
Dan Capone		Operations Section Chief						
Joe Victory		Operations Section Chief						
Dan Zahner	Field Team Lead							
Jose Aguilera		SOTF#7						
			8. Ac	etivity	Log			
	Manuary Lake Manuary Lake Neels and Manuary Lake					LAT	LAT	
Activity Area	Morrow Lake, Morrow Lake Neck and Morrow Lake Delta				Various	Various		
		OH IMBA	AMED.				(DD.MMMM)	(DD.MMMM)
OIL OBSERVED	EXTENT OF OIL IMPACTED NA							
	DENSITY OF OIL /SHEEN NA							
Total Collection	22 monitoring points NA							
Points Total Boom Deployed								
Activity	START SOTF Team # 7 Activity: Team SOTF #7 launched out of E4 and conducted poling ops. A total of 22 poling locations were assessed in the Morrow Lake Delta. Poling Morrow Lake Delta – Total: 22 with 3 Heavy, 5 Moderate, 10 Light, 4 None Heavy locations D40, D42 and D43. Moderate locations D46, D41, N02, N03 and N05 Some sheen due to jet boat maneuvering. All locations passed the temperature requirement. Team also mobilized to C5 launch pad to deploy aluminum box for the agitation study, however operation was canceled. E4 containment System: Crew utilized underwater camera to inspect boom/curtains at configuration E including collection point. Crew utilizes an inspection log to record observations and any adjustments needed.							
	None							